

# Repair Your Toyota Tacoma or Ford Overhead Compass Display

## WE WILL REPAIR IT *BETTER* THAN NEW!

**Siliconmethod.com:** We can repair your Toyota Tacoma compass / temperature display (accessory meter) or Ford Explorer / Expedition / Sport Trac overhead display.

What generally happens is that one or more tiny components (surface mount resistors and/or transistors) have separated from the circuit board, and the display darkens or operates intermittently. However, we will repair it for you in a manner much better than the original factory design! We install new power resistors on your circuit board, not just the ones that failed. We also embed wire leads under the resistors to act as heatsinks. This has a dual purpose to lift the resistor off the board and allow airflow, further cooling the components... preventing the issue from occurring again.

We test the unit and if necessary troubleshoot other component failures. After the repair is complete, we clean the glass and plastic interior surfaces.

**We only charge \$49 for the service**, and that includes return shipping. Overnight option available.



## WE GUARANTEE IT.

If your display fails again due to power resistor issues within 3 years of our original work, we will repair it and ship it back to you for FREE!

### HERE'S THE PROCESS:

1. You pull the console and ship it to us (it's very easy to remove).
2. We make the repair using new components and heatsinks. The current condition of your circuit board doesn't matter!
3. We then ship the part back to you. Turnaround time is usually 2-3 days, not including shipping. Reinstall your console, and done.

**Email:** [repair@siliconmethod.com](mailto:repair@siliconmethod.com)

**See our website for more details:** [www.siliconmethod.com](http://www.siliconmethod.com)

**We also offer referral bonuses:** For every repair you send our way, we will give you \$5.00! (PayPal account required). You make money, a friend saves money and time, and the display is permanently repaired!